

Republika ng Pilipinas Lungsod Quezon SANGGUNIANG PANLUNGSOD (City Council)

PR98-287

15th Regular Session

RESOLUTION NO. SP-1043, S-98

A RESOLUTION STRONGLY URGING THE CITY ENGINEER, CITY ELECTRICIAN, AND BUILDING OFFICIAL OF QUEZON CITY TO CONDUCT A MASSIVE INSPECTION OF ELECTRICAL INSTALLATIONS/CONNECTIONS WITHIN THE QUEZON CITY HALL COMPOUND TO IMMEDIATELY DETECT FAULTY WIRINGS AND INSTALL PRECAUTIONARY MEASURES TO AVOID FUTURE FIRE INCIDENTS.

Introduced by Councilor WILMA AMORANTO SARINO.
Co-Introduced by Councilors Winston "Winnie" T. Castelo,
Godofredo T. Liban II, Marciano P. Medalla, Eric Z. Medina
and Julian M.L. Coseteng.

WHEREAS, the recent occurrence of fire that gutted the main building of the Quezon City Hall was due to faulty wiring, as alleged;

WHEREAS, there is a need to conduct massive inspection of electrical connections within and around the Quezon City Hall premises to detect possible or any faulty wirings and thus avoid the occurrence of unfriendly fire causing loss of properties and important records;

NOW, THEREFORE,

BE IT RESOLVED, BY THE CITY COUNCIL OF QUEZON CITY IN SESSION ASSEMBLED, to urge, as it does hereby urge, the City Engineer, City Electrician, and Building Official of Quezon City to conduct a massive inspection of electrical installations/connections within the Quezon City Hall compound to immediately detect faulty wirings and install precautionary measures to avoid future fire incidents.

ADOPTED:

November 10, 1998.

ELIZABETH M. DELARMENTE
Acting Presiding Officer

ATTESTED:

EUGENIO V. JURILLA City Council Secretary

gra